Note : This document has been translated from the Japanese original for reference purposes only. In the event of any discrepancy between this translated document and the Japanese original, the original shall prevail.

November 24, 2026

Company name: Chubu Steel Plate Co., Ltd.
Name of representative: Daigou Kaneko, Representative Director and President
(Securities code: 5461; Tokyo Stock Exchange, Nagoya Stock Exchange)
Inquiries: Susumu Matsuda, Executive Director
(Telephone: +81-52-661-3811)

Notice Regarding the Accident in our plant

At approximately 8:25 a.m. on Tuesday, November 24, a steam explosion occurred at the slag processing area of our plant. We sincerely apologize to nearby residents and all those concerned for the inconvenience and concern this incident has caused.

We would like to provide the following information currently available regarding the incident.

1. Location of Occurrence
   Steelmaking slag processing area, our plant 5-1 Kousu-dori, Nakagawa-ku, Nagoya, Aichi Prefecture

2. Date and Time of Occurrence
   Approximately 8:25 a.m. on Tuesday, November 24, 2026

3. Overview of the Accident
   A steam explosion occurred at the slag processing area within our plant. Part of the building was damaged. No fire resulted from the explosion.
   The cause of the incident is currently under investigation.

4. Status of Damage
   One employee of a contractor sustained minor injuries.
   As for property damage, the building was damaged, and we are currently confirming the full extent of the damage.

5. Impact on Future Operations and Performance
   Operations at the steelmaking plant are currently suspended while safety checks and an investigation are conducted. The rolling mill will continue operating for the time being using stockpiled slabs and other materials.
   Should we determine that this incident is likely to have a material impact on our business results, we will make an announcement promptly.